SVA
SVA Industrie Fernseh GmbH

THERMAL IMAGING | THERMOVISION

Thermal imaging is a very effective, preventive method to discover soft spots at the oven and its technical components and assemblies.

Discovering anomalousness in there beginning (before it is visible to your naked eye) enables you to initiate corrective action instead of expensive failure.

We generate thermal imaging experts report of the oven, it's assemblies and its electrical components.





Thermovision als effektive vorbeugende Maßnahme und zur Erkennung bestehender Schwachstellen am äußeren Aufbau von Ofensystemen und zuarbeitender Komponenten.

Durch die Entdeckung von Anomalien, die für das bloße Auge meist unsichtbar sind, ermöglicht die Thermografie die Durchführung von Korrekturmaßnahmen, bevor es zu teuren Systemausfällen kommt.

Wir erstellen thermografische Gutachten sowohl von Öfen, deren Versorgungssystemen als auch von den dazu gehörenden elektrischen Komponenten.





SVA Industrie Fernseh GmbH

Marie–Curie–Straße 11 · 40721 Hilden · Germany · Tel.: +49 (0) 2103 – 33 55 00 · Fax: +49 (0) 2103 – 33 55 01
Internet: www.sva–hilden.de · e-mail: info@sva–hilden.de